




**Manassas Consulting, LLC.**  
375 S Pacific Ave  
Pittsburgh, PA 15224  
Telephone:  
**+1-412-235-1520**  
<http://manassasconsulting.com>

**Notice:**  
Web accessible material accompanying this drawing including high density PhotoSurvey™ Inspection Tool images, and with this drawing may be accessed at <http://ohc.manassasconsulting.com> during the project.  
© 2020 Manassas Consulting LLC. All rights reserved. This drawing is an instrument of service.



South Facade - left & Sidewalls above lower roof



CAD FILE INFORMATION

REVISION NUMBER	REVISION DESCRIPTION	REVISION DATE
▲		
▲		
▲		
▲		
▲		
▲		
▲		
▲		
▲		
▲		

DATE	
------	--

CONTRACT	A/E		
CONSTRUCT.	PRIME A/E		
ADDRESS	STREET	CITY	STATE
ADDRESS	STREET	CITY	STATE
ADDRESS	STREET	CITY	STATE
ADDRESS	STREET	CITY	STATE
ADDRESS	STREET	CITY	STATE
ADDRESS	STREET	CITY	STATE
NAME	Benjamin Lundy House		
ADDRESS	306 Union Street		
CITY	Mt Pleasant		
STATE	OH		
ZIP CODE	43080		
BUILD NO.			
ADDP. FACILITY			
ADDP. FAC. NO.			
TITLE	Masonry Restoration		
DESCRIPTION	Existing Condition Survey		
SUBMISSION	100%	SUB. DATE	8/15/2020
DRAWN BY	Battle Brown		
DATE DRAWN	8/12/2020		
FILE NAME	AV105.dwg		
FLOOR NO.			
TITLE	South Facade - Left		
DISCIPLINE	AV	SHEET TYPE	1
SEQUENCE			05

Notice:  
PhotoDrawing™ blueprints on these pages are produced under one or more of the following U.S. Patents 8,194,074, 8,542,233, 8,866,814, and 9,715,755; and patents pending.  
<http://manassasconsulting.com>  
Do not remove this notice.

